

# Final Reclamation Inspection

September 6th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 322814

Inspection Document #: 701900690

SENE Section 13 T5N R65W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Conquest Holton 8-13  
Location ID: 322814




**Photo 1.** 2021 aerial imagery of the well pad, access road and tank battery.

Inspection Photos  
Location Name: Conquest Holton 8-13  
Location ID: 322814




**Photo 2.** Overview photo of the well pad, access road and reference area taken from the western edge facing east using a drone. Note: well pad and access road appear consistent with adjacent crop reference area.

Inspection Photos  
Location Name: Conquest Holton 8-13  
Location ID: 322814



**Photo 3.** Overview photo of the tank battery taken from directly above the disturbance using a drone. Note: tank battery falls within unplanted area between two corn crop fields.

Inspection Photos  
Location Name: Conquest Holton 8-13  
Location ID: 322814



**Photo 4.** Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Conquest Holton 8-13  
Location ID: 322814



**Photo 5.** Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery has large pile of manure and is dominated by kochia.