

Final Reclamation Inspection

September 6th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 333191

Inspection Document #: 701900691

NESE Section 13 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Watters 13-10B
Location ID: 333191



Photo 1. 2021 aerial imagery of the well pad and tank battery.

Inspection Photos
Location Name: Watters 13-10B
Location ID: 333191



Photo 2. Overview photo of the well pad taken from the western edge facing east. Note: well pad appears consistent with adjacent reference area (see photo 3).

Inspection Photos
Location Name: Watters 13-10B
Location ID: 333191



Photo 3. Well pad reference area.

Inspection Photos
Location Name: Watters 13-10B
Location ID: 333191



Photo 4. Overview photo of the tank battery taken at ground level from the northern edge facing south. Note: tank battery disturbance falls within an unplanted area between two corn crop fields.

Inspection Photos
Location Name: Watters 13-10B
Location ID: 333191



Photo 5. Cardinal photos taken from the middle of the tank battery.
Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Watters 13-10B
Location ID: 333191



Photo 6. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery shows minimal desirable species and is dominated by a colorado list C invasive species: puncture vine.