

Final Reclamation Inspection

September 7th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 319054

Inspection Document #: 701900837

NENE Section 27 T6N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Leffler 1-27
Location ID: 319054




Photo 1. 2021 aerial imagery of the well pad, tank battery and access road. Note: well pad and tank battery shared a disturbance pad.

Inspection Photos
Location Name:Leffler 1-27
Location ID: 319054




Photo 2. Overview photo of the well pad, tank battery and access road taken from the southern edge facing north using a drone. Note: well pad and tank battery appear consistent with adjacent crop reference area.