

# Final Reclamation Inspection

August 17, 2022  
and  
December 27, 2022

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 482899

Inspection Document #: 697504468

Weld County, CO

NENE Section 33 T2N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: 33-2N-68W NENE Tank Battery Loc

Location ID: 482899



**Photo 1.** Photo taken from an unused tank battery, facing West. Photo illustrates equipment has not been removed.



**Photo 2.** Photo taken from an unused tank battery, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: 33-2N-68W NENE Tank Battery Loc  
Location ID: 482899



**Photo 3.** Close up photo taken illustrating the Operator ownership.



## Inspection Photos

Location Name: 33-2N-68W NENE Tank Battery Loc

Location ID: 482899



**Photo 4.** Photo taken from an unused tank battery, facing South. See comments under Photo 1.



**Photo 5.** Photo taken from an unused tank battery, facing North. See comments under Photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504468

## Inspection Photos

Location Name: 33-2N-68W NENE Tank Battery Loc

Location ID: 482899



**Photo 6.** COGCC GISOnline aerial imagery from 2019. The red circle shows all the equipment from Photos 1-5; the orange arrow is pointing to more related equipment- see the following photo.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697504468



## Inspection Photos

Location Name: 33-2N-68W NENE Tank Battery Loc

Location ID: 482899



**Photo 7.** Photo taken south of the tank battery illustrated in Photos 1-5, facing East. Photo illustrates related KPK equipment that shall be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697504468