

Final Reclamation Inspection

September 18th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323117

Inspection Document #: 701900720

SESW Section 22 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Virginia 1-22
Location ID: 323117



Photo 1. 2021 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Virginia 1-22
Location ID: 323117



Photo 2. Overview photo of the well pad and access road taken from the southern edge facing north using a drone. Note: slight corn stunting exist in the entire Northwest corner of the crop field and is not associated with oil and gas operations.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number:
701900720

Inspection Photos
Location Name: Virginia 1-22
Location ID: 323117



Photo 3. Ground photo of the tank battery taken from the eastern edge facing west. Gravel remains at the tank battery location. The land owner is using the area to store equipment.