

Final Reclamation Inspection

September 18th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 327061

Inspection Document #: 701900734

SENE Section 16 T6N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: State Lease 81, 42-16
Location ID: 327061



Photo 1. 2020 aerial imagery of the well pad and tank battery. Note: could not identify access road from historical imagery.

Inspection Photos
Location Name: State Lease 81, 42-16
Location ID: 327061




Photo 2. Overview photo of the well pad and reference area taken from the southern edge facing north using a drone. Note: well pad appears consistent with adjacent crop reference area.

Inspection Photos
Location Name: State Lease 81, 42-16
Location ID: 327061



Photo 3. Overview photo of the tank battery taken at ground level from the eastern edge facing west. Note: tank battery falls within a corner crop area.

Inspection Photos
Location Name: State Lease 81, 42-16
Location ID: 327061



Photo 4. Cardinal photos taken from the middle of the tank battery.
Left photo facing north, right photo facing east.

Inspection Photos
Location Name: State Lease 81, 42-16
Location ID: 327061



Photo 5. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery has a large pile of dirt in the middle of the disturbance and portions of the northern access road remain unreclaimed with gravel.