

Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334770

Location Name: SHIDELER-67S92W/20SWNW

Inspection Document #: 702801070

Garfield County, CO

SWNW Section 20 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SHIDELER-67S92W/20SWNW
Location ID: 334770



Photo 1. Photo taken from the east shows an overview of the location.



Inspection Photos
Location Name: SHIDELER-67S92W/20SWNW
Location ID: 334770



Photo 2. Photos show production areas. Note lack of tank battery sign (left).



Inspection Photos

Location Name: SHIDELER-67S92W/20SWNW

Location ID: 334770



Photo 3. Photos show open ended piping at separators (left) and tank battery (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801070

Inspection Photos

Location Name: SHIDELER-67S92W/20SWNW

Location ID: 334770



Photo 4. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801070

Inspection Photos

Location Name: SHIDELER-67S92W/20SWNW

Location ID: 334770



Photo 5. Photos show interim areas at the south (left) and north (right) appear dominated by native and introduced perennial grasses. Snow cover and dormant season prevented full vegetation assessment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801070