

Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334790

Location Name: SHIDELER-67S92W/19SWSE

Inspection Document #: 702801076

Garfield County, CO

SWSE Section 19 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SHIDELER-67S92W/19SWSE
Location ID: 334790



Photo 1. Photo taken from the south shows an overview of the location.

Inspection Photos
Location Name: SHIDELER-67S92W/19SWSE
Location ID: 334790



Photo 2. Photo shows production areas.

Inspection Photos
Location Name: SHIDELER-67S92W/19SWSE
Location ID: 334790



Photo 3. Photos show interim areas at the southeast (left) and west (right) appear dominated by introduced perennial grasses. Snow cover and dormant season prevented full vegetation assessment. Note also storage of unused pipe equipment.



Inspection Photos
Location Name: SHIDELER-67S92W/19SWSE
Location ID: 334790



Photo 4. Photos show stormwater BMPs at the south of the location.

