

Inspection Photos

API: 071-07767

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/28/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07767 | Date: 12/28/2022

Inspection Photos



Photo 1. Facing west at the location. The area of erosion has not been repaired (area circle). Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07767 | Date: 12/28/2022

Inspection Photos



Photo 2. Facing west at the location. There is also an erosion channel shown at red arrow which is covered in snow. Will likely need to wait fr snow to melt to complete repairs.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07767 | Date: 12/28/2022