

Inspection Photos

API: 071-07509

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/28/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07509 | Date: 12/28/2022

Inspection Photos



Photo 1. Facing southeast along the main access road. This culvert has filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07509 | Date: 12/28/2022

Inspection Photos



Photo 2. Another culvert further down the road has filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07509 | Date: 12/28/2022

Inspection Photos



Photo 3. Facing southwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07509 | Date: 12/28/2022