

Inspected Facilities

Facility ID: 241251 Type: WELL API Number: 123-09039 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
Follow up inspection to Doc# 693505726 in response to FIRR #403215847. Based on document submitted by operator, operator appears to be trying to have electric complany remove equipment. Operator well need to Email response to inspector once recieved and inform inspector when equipment is removed for inspection of site.(photos attached to FIRR)	silverr	12/29/2022