

Pit Status Evaluation Form

Pit Overview:

Pit Name: Box Elder	Facility ID: 119204
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: Union Pacific Resources Company-91100	
Updated Operator: Location Operated by Great Western Oil and Gas	
Form 15 Pit Permit Doc #: NA	Permit Date: NA
Related Facilities: Location 476596; Well 05-001-06198 (PA 1/6/20); Well 05-001-06919 (PA 10/25/01); Off Loc Flowline 476623	

County: Adams			
Township: 1S	Range: 66W	Section: 35	QQ: SEE
Original Latitude/ Longitude: 39.923690 / -104.734660			
Updated Latitude/ Longitude: /			
Basis for Location Change:			
No change made. 2 unstatused pits show up at the SE corner of a pit visible in the 1990s COGCC aerial imagery (gone in 2009).			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|----------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input type="checkbox"/> | Field Inspection(s) – Doc #: | Date: |
| | Doc #: | Date: |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 113807 | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Left Pit Status Date as 9/23/1999 since it is a duplicate record.

Pit Status Review Summary:

This pit record is a duplicate of 113807, likely created during the pit inventory representing production from 001-06918 (Box Elder #4); all records, including permit docs and inspections are included in file for 113807, which is related to 001-06918 (Box Elder #5). Therefore, this pit can be administratively closed, and all relevant data review included in the review of 113807.