

# Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334630

Location Name: SHIDELER-67S93W/25SENE

Inspection Document #: 702801084

Garfield County, CO

SWNW Section 30 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SHIDELER-67S93W/25SENE  
Location ID: 334630



**Photo 1.** Photos show an overview of the location (left) and production areas (right).



Inspection Photos

Location Name: SHIDELER-67S93W/25SENE

Location ID: 334630



Photo 2. Photos show downward erosion/undermining of the berm at the south of the location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801084

## Inspection Photos

Location Name: SHIDELER-67S93W/25SENE

Location ID: 334630



**Photo 3.** Photos show interim areas at the north of the location. Perennial grasses are present, however low residual cover from grazing and dormant season prevented full vegetation assessment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801084