

Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334232

Location Name: SHIDELER FEDERAL-67S93W/26SESE

Inspection Document #: 702801088

Garfield County, CO

SESE Section 26 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SHIDELER FEDERAL-67S93W/26SESE

Location ID: 334232



Photo 1. Photo taken from the north shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801088

Inspection Photos

Location Name: SHIDELER FEDERAL-67S93W/26SESE

Location ID: 334232



Photo 2. Photos show tank battery sign absent (left) and bull plugs not installed on tank drain lines (right).

Inspection Photos

Location Name: SHIDLER FEDERAL-67S93W/26SESE

Location ID: 334232



Photo 3. Photos show bull plugs not installed on tank drain lines (left) and open ended piping at tank battery (both).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801088

Inspection Photos

Location Name: SHIDELER FEDERAL-67S93W/26SESE

Location ID: 334232



12/27/22
+39.410600,-107.735144
201° S

Photo 4. Photo shows interim areas at the south of the location. Snow cover and dormant season prevented full vegetation assessment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801088