

Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334613

Location Name: SHIDELER-67S93W/25NWSW

Inspection Document #: 702801090

Garfield County, CO

NWSW Section 25 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SHIDELER-67S93W/25NWSW
Location ID: 334613



Photo 1. Photo taken from the west shows an overview of the location.



Inspection Photos
Location Name: SHIDELER-67S93W/25NWSW
Location ID: 334613



Photo 2. Photos show tank battery sign absent (left) and bull plugs not installed on tank drain lines (right).

Inspection Photos
Location Name: SHIDELER-67S93W/25NWSW
Location ID: 334613



Photo 3. Photos show open ended piping at separators (left) and tank battery (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801090

Inspection Photos
Location Name: SHIDELER-67S93W/25NWSW
Location ID: 334613



Photo 4. Photo shows interim areas at the west of the location appear dominated by introduced perennial grasses. Snow cover and dormant season prevented full vegetation assessment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801090