

# Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334618

Location Name: HMU Federal/24-13A1 (D25W)

Inspection Document #: 702801092

Garfield County, CO

NWNW Section 25 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HMU Federal/24-13A1 (D25W)  
Location ID: 334618



**Photo 1.** Photo taken from the north shows an overview of the location.



Inspection Photos  
Location Name: HMU Federal/24-13A1 (D25W)  
Location ID: 334618



**Photo 2.** Photos show tank battery sign absent (left) and bull plugs not installed on tank drain lines (right).



Inspection Photos  
Location Name: HMU Federal/24-13A1 (D25W)  
Location ID: 334618



**Photo 3.** Photo shows open ended piping at tank battery.

Inspection Photos  
Location Name: HMU Federal/24-13A1 (D25W)  
Location ID: 334618



**Photo 4.** Photo shows interim areas at the north of the location appear dominated by introduced and native perennial grasses.

