

Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334336

Location Name: SHIDELER-67S93W/36NENW

Inspection Document #: 702801094

Garfield County, CO

NENW Section 36 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: SHIDELER-67S93W/36NENW

Location ID: 334336



Photo 1. Photos show tank battery sign absent (left) and bull plugs not installed on tank drain lines (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801094

Inspection Photos
Location Name: SHIDELER-67S93W/36NENW
Location ID: 334336



Photo 2. Photo shows open ended piping on separator line.



Inspection Photos

Location Name: SHIDELER-67S93W/36NENW

Location ID: 334336



Photo 3. Photo shows interim areas at the north of the location appear dominated by introduced and native perennial grasses.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801094