

# Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334270

Location Name: J25W Water Storage Pit/1

Inspection Document #: 702801096

Garfield County, CO

NWSE Section 25 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: J25W Water Storage Pit/1  
Location ID: 334270



**Photo 1.** Photo taken from the north shows an overview of the location. Gate open, livestock present.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801096



Inspection Photos  
Location Name: J25W Water Storage Pit/1  
Location ID: 334270



**Photo 2.** Photo taken from the east of the location facing west (on location) shows a cut/exposed pipe left on location.



**Photo 3.** Photo taken from the east of the location facing east shows where the pipe pictured in Photo 2 continues off location.



Inspection Photos  
Location Name: J25W Water Storage Pit/1  
Location ID: 334270



**Photo 4.** Photo taken from the east of the location facing east shows where the pipe pictured in Photo 2 continues off location.