

Final Reclamation Inspection

September 18th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 329287

Inspection Document #: 701900735

NWNW Section 14 T6N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Jeff 1
Location ID: 329287



Photo 1. 2020 aerial imagery of the well pad, access road and tank battery.



Photo 2. Overview photo of the well pad taken at ground level from the northern edge facing south.



Photo 3. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Jeff 1
Location ID: 329287



Photo 4. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with adjacent crop reference area. See photo 5.

Inspection Photos
Location Name: Jeff 1
Location ID: 329287



Photo 5. Well pad reference area.



Photo 6. Overview photo of the tank battery taken at ground level from the eastern edge facing west. Note: gravel remains at the tank battery location.