

# Inspection Photos

12/27/2022

Operator: LARAMIE ENERGY LLC - 10433

Location #335482

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335482



**Photo 1:** Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335482



December 27, 2022



December 27, 2022

**Photo 2:** See comment under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335482



**Photo 3:** Photo taken from the Location, facing north. Photo shows cut-slopes of the Location. Resolution documents submitted by Operator indicate erosion was repaired, followed by an application of straw mulch and hydromulch. Photo shows large areas of the cut slope where BMPs are in disrepair, and erosion degradation is recurring: BMPs implemented have not been maintained, and do not appear to be adequate for the site's conditions

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335482



**Photo 4:** See comments under photo 3.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335482



**Photo 5:** Photo taken from the cut slopes of the Location. Photo example showing erosion degradation at the cut slopes; specifically, photo shows sediment covering the mulch; BMPs implemented have not been maintained, and do not appear to be adequate for the site's conditions