

# Inspection Photos

12/27/2022

Operator: NONSUCH NATURAL GAS INC

#10163

Location #324169

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #324169



December 27, 2022

**Photo 1:** Overview of the Location- limited visibility inspection due to snow cover.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: NONSUCH NATURAL GAS INC #10163  
Location #324169



**Photo 2:** Photos show wildlife protection devices at secondary containment remain missing, or in disrepair.



## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #324169



**Photo 3:** Photo shows example areas of slopes that were exposed/visible on the Location unable to observe evidence that stormwater and erosion control BMPs were implemented. Erosion within areas remains apparent.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources