

# Inspection Photos

12/27/2022

Operator: LARAMIE ENERGY LLC #10433

Location #335647

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location #335647



December 27, 2022



December 27, 2022

**Photo 1:** Photos 1-2 taken from the northwest end of the Location. Photos provide an overview of the location from northeast, east, southeast to southwest.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location #335647



December 27, 2022



December 27, 2022

**Photo 2:** See comment under photo 1.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location #335647



**Photo 3:** Photo taken from the topsoil stockpile on the north end of the Location. BMPs to stabilize topsoil stockpile, and to protect from wind and water erosion remain missing or insufficient.





Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location #335647



**Photo 4:** Photo taken from the topsoil stockpile on the north end of the Location. BMPs to stabilize topsoil stockpile, and to protect from wind and water erosion remain missing or insufficient.