

Inspection Photos

API: 071-09347

Operator: OGRIS OPERATING LLC

Inspection Date: 12/30/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09347 | Date: 12/30/2022

Inspection Photos



Photo 1. Facing southwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09347 | Date: 12/30/2022

Inspection Photos



Photo 2. The electric fence is in disrepair around the pit. A more robust fencing should be considered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09347 | Date: 12/30/2022

Inspection Photos



Photo 2. On the south side of the road is a discharge point. The electric fence is in disrepair and should be reinstalled or removed if not required.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09347 | Date: 12/30/2022