

Inspection Photos

API: 071-09496

Operator: OGRIS OPERATING LLC

Inspection Date: 12/30/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09496 | Date: 12/30/2022

Inspection Photos



Photo 1. Facing toward the wellsite. There is oil stained soil around the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09496 | Date: 12/30/2022

Inspection Photos



Photo 2. There is water around at the meter shed which appears to be leaking..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09496 | Date: 12/30/2022

Inspection Photos



Photo 2. The electric fence is in disrepair around the pit. A more robust fencing should be considered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09496 | Date: 12/30/2022