

Inspection Photos

API: 071-09604

Operator: OGRIS OPERATING LLC

Inspection Date: 12/30/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09604 | Date: 12/30/2022

Inspection Photos



Photo 1. Facing toward the wellsite. The electric fence is in disrepair around the pit. A more robust fencing should be considered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09604 | Date: 12/30/2022

Inspection Photos



Photo 2. There are stained soils at the meter shed that should be cleaned up and equipment inspected for leaks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09604 | Date: 12/30/2022