

Final Reclamation and Stormwater Inspection

Date: 12/28/2022

Operator: KP KAUFFMAN COMPANY - 46290

Location ID: 313843

Inspection Document #: 696105666

Morgan County, CO

NWNE Section 32 T2N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Boxer Unit # 25
Location ID: 313843



Photo 1. Facing east from western portion of location. Photo shows unused equipment (e.g. pipe and sucker rod) on location. This is considered unused equipment and needs to be removed.

Inspection Photos
Location Name: Boxer Unit # 25
Location ID: 313843



Photo 2. See comments in photo 1.

Inspection Photos
Location Name: Boxer Unit # 25
Location ID: 313843



Photo 3. Facing west from the eastern portion of the well location. Red arrow illustrates no visible netting/wildlife protection around open tank.

Inspection Photos
Location Name: Boxer Unit # 25
Location ID: 313843



Photo 4. Facing east from the eastern portion of the well location. Photo illustrates debris (e.g. barrel) highlighted in red; and evidence of soil degradation/erosion due to apparent stormwater runoff. Location will be re-inspected at a later date to assess soil conditions as snow cover blocked view of adjacent lands.