

Inspection Photos
Location Name: Leggit 1-5H
Location ID: 428225



Photo 1 – Heater Treater and Gas Meter



Photo 2 – Wellhead

Inspection Photos
Location Name: Leggit 1-5H
Location ID: 428225



Colorado Oil and Gas Conservation Commission
40.60228, -104.12559, 4853.7ft, 96°
12/14/2022 12:21:42

Photo 3 – Unused Wellhead Parts



Colorado Oil and Gas Conservation Commission
40.60228, -104.12559, 4854.3ft, 97°
12/14/2022 12:21:45

Photo 4 – Unused Rods

Inspection Photos
Location Name: Leggit 1-5H
Location ID: 428225



Photo 5 – Stained Soil at Gas Engine



Photo 6 – Unused Wellhead Parts

Inspection Photos
Location Name: Leggit 1-5H
Location ID: 428225



Photo 7 – ECD and Flare



Photo 8 – Tank Battery

Inspection Photos
Location Name: Straudinger 1-31H
Location ID: 424744



Photo 9 – Tank Battery Sign