


Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Colorado Oil and Gas Conservation Commission
40.59774, -104.06238, 4869.5ft, 265°
12/27/2022 13:09:27



Colorado Oil and Gas Conservation Commission
40.59789, -104.06241, 4882.6ft, 203°
12/27/2022 13:09:47

Photo 1 – Unmarked 1” Riser at 2-6 Wellhead

Photo 2 – 2-6 Gas Engine

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327




Photo 3 – 2-6 Wellhead

Photo 4 – 2-3 Wellhead – Stained Soil

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327




Photo 5 – Stained Soil at 2-6 Wellhead

Photo 6 – 2-6 Wellhead – Stained Soil and Oily Waste

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 7 – 2-6 Wellhead



Photo 8 – 2-6 Wellhead

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 9 – 2-1 Gas Engine

Photo 10 – 2-1 Wellhead

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Colorado Oil and Gas Conservation Commission
40.59792, -104.06221, 4798.6ft, 55°
12/27/2022 13:15:13



Colorado Oil and Gas Conservation Commission
40.59763, -104.06208, 4886.8ft, 98°
12/27/2022 13:15:36

Photo 11 – ECD and Flare

Photo 12 – Tank Battery Sign

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 13 – Tank Battery

Photo 14 – Heater Treaters

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Colorado Oil and Gas Conservation Commission
40.59735, -104.06201, 4879.7ft, 85°
12/27/2022 13:16:15



Colorado Oil and Gas Conservation Commission
40.59736, -104.06202, 4877.8ft, 145°
12/27/2022 13:16:12

Photo 15 – Heater Treaters

Photo 16 – Gas Meters