

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 1 – Wellhead

Photo 2 East Side of Pumping Unit

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Colorado Oil and Gas Conservation Commission
40.60377, -104.06658, 4862.0ft, 232°
12/27/2022 13:02:59



Colorado Oil and Gas Conservation Commission
40.60377, -104.06659, 4864.2ft, 242°
12/27/2022 13:03:03

Photo 3 – East Side Gear Box

Photo 4 – East Side Gear Box

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 5 – Stained Soil at Exhaust



Photo 6 – West Side of GearBox

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 7 – West Side of Gear Box

Photo 8 – West Side of Gear Box

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 9 – West Side of Gear Box



Photo 10 – Exhaust

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 11 – Stained Soil at Gas Engine

Photo 12 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 13 – Flare and ECD



Photo 14 – Heater Treater

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Colorado Oil and Gas Conservation Commission
40.60342, -104.067, 4858.5ft, 195°
12/27/2022 13:05:56



Colorado Oil and Gas Conservation Commission
40.60341, -104.06703, 4860.4ft, 170°
12/27/2022 13:06:03

Photo 15 – Tank Battery

Photo 16 – Tank Battery Sign