

Inspection Photos

API: 071-07893

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/4/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07893 | Date: 1/4/2023

Inspection Photos



Photo 1. Facing northeast along the main road. There is erosion along this area of road that needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07893 | Date: 1/4/2023

Inspection Photos



Photo 2. There is a damaged culvert near the location which should be cut off and armored with outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07893 | Date: 1/4/2023

Inspection Photos



Photo 3. Facing northwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 071-07893 | Date: 1/4/2023