

# Inspection Photos

API: 071-09274

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/4/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09274 | Date: 1/4/2023

## Inspection Photos



**Photo 1.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09274 | Date: 1/4/2023



## Inspection Photos



**Photo 2.** Facing toward the lined pit. The pit liner is torn in numerous places.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09274 | Date: 1/4/2023



## Inspection Photos



**Photo 2.** There are oil stained soils at the engine skid that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09274 | Date: 1/4/2023