

Interim Reclamation and Stormwater Inspection

Date: 01/05/2023

Operator: SUMMIT OIL AND GAS LLC - 10774

Location ID: 465272

Inspection Document #: 696105672

Weld County, CO

SWSE Section 12 T7N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Castor 7-59/12
Location ID: 465272



Photo 1. Facing east towards tank batteries. Photo illustrates crude released from thief hatches and dripping down the sides of the batteries.

Inspection Photos
Location Name: Castor 7-59/12
Location ID: 465272



Photo 2. See comments in Photo 1.

Inspection Photos

Location Name: Castor 7-59/12

Location ID: 465272



Photo 3. Facing southwest/south towards tank battery. Red outline shows crude spill on northern/middle tank.

Inspection Photos
Location Name: Castor 7-59/12
Location ID: 465272



Photo 4. Facing northeast/northwest towards separator at the north end of the location. Photos illustrates a failed gasket that resulted in fluid exiting the equipment.

Inspection Photos
Location Name: Castor 7-59/12
Location ID: 465272



Photo 5. Facing southeast/northeast at the separators towards the north end of the location. Photo illustrates tumbleweeds accumulated in and around equipment. This is considered debris, presents a potential fuel source for fire, and needs to be disposed of.

Inspection Photos
Location Name: Castor 7-59/12
Location ID: 465272



Photo 6. Facing northwest at tank battery. Photo illustrates tumbleweeds accumulated in and around equipment. This is considered debris, presents a potential fuel source for fire, and needs to be disposed of.

Inspection Photos
Location Name: Castor 7-59/12
Location ID: 465272



Photo 7. Facing west and northwest from location. Photos illustrate piles of supplies and smaller equipment being stored on location. Snow on top of these indicates they have been there for some time and need to be stored off location if not currently being used.