

FORM
43

Rev
02/17

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

05/10/2022

Document Number:

403043325

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of Ground Water Sampling Form

Submit a New Water Quality Sample Location to the COGCC for rules 317B, 318A.5, 608, 609.d(3)., Condition of approval, or other reason.

Submit a New Water Quality Sample to the COGCC for rules 317B, 318A.5, 608, 609.d(3)., Condition of approval, or other reason.

Operator Information

OGCC Operator Number: 10705 Contact Person: Mackenzie Smith
Company Name: EVERGREEN NATURAL RESOURCES LLC Phone: (303) 2848820
Address: 1875 LAWRENCE ST STE 1150 Fax: ()
City: DENVER State: CO Zip: 80202 Email: mackenzie.smith@enrllc.com

Well/Facility Information

API Number: 05 - - OGCC Facility ID: 288825
Well/Facility Name: CACTUS FLOWER Well/Facility Number: 13-24
Location QtrQtr: NWSW Section: 24 Township: 32S Range: 68W Meridian: 6
County: LAS ANIMAS Field Name: PURGATOIRE RIVER
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: EVERGREEN NATURAL RESOURCES LLC Agent Name: Mackenzie Smith Title: Production Engineer
Phone Number: 303-2848820 Email: mackenzie.smith@enrllc.com

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 276908 Facility Name: CACTUS FLOWER 13-24 Facility Type: Oil and Gas Well
Location: QtrQtr: NWSW Sec: 24 Twp: 32S Range: 68W Meridian: 6
County Name: LAS ANIMAS Latitude: 37.243170 Longitude: -104.954270

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 98633 Document Name: Size of file in bytes: 11235 File Name: 276908 - EDD2 272022.xlsx
SampleType: Matrix:
Facility ID: 276908 Sample ID: 635883 Sample Name: Cactus Flower 13-24 Sample Date: 12/13/2021
Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-156773-7

Batch ID: 98632 Document Name: Size of file in bytes: 39963 File Name: 276908 - EDD1 12302021.xlsx

SampleType: Matrix:

Facility ID: 276908 Sample ID: 635882 Sample Name: Cactus Flower 13-24 Sample Date: 12/13/2021

Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample

Project Number: Remediation Number: Complaint Number: NOAV Number:

Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-156773-7

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
276908	403043335	276908 - report2 272022.pdf	Analytical Laboratory Report	PDF
276908	403043329	276908 - report1 12302021.pdf	Analytical Laboratory Report	PDF

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	01/06/2023
Total: 1 comment(s)		