

Inspection Photos

January 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335076

Location Name: CLOUGH-66S94W/29SENW

Inspection Document #: 702801098

Garfield County, CO

SENW Section 29 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/29SENW
Location ID: 335076



Photo 1. Photo taken from the east shows an overview of the location.

Location ID: 335076



Photo 2. Photos show stained soil beneath chemical injection equipment at the separators.

Inspection Photos
Location Name: CLOUGH-66S94W/29SENW
Location ID: 335076



Photo 3. Photos show production areas and unused equipment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801098

Inspection Photos
Location Name: CLOUGH-66S94W/29SENW
Location ID: 335076



Photo 4. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801098

Inspection Photos
Location Name: CLOUGH-66S94W/29SENW
Location ID: 335076



Photo 5. Photo shows an example of the interim areas. Vegetation appears dominated by sparse introduced perennial grasses and native shrubs. Snow cover and dormant season prevented full assessment.

