

Inspection Photos

January 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 311564

Location Name: CLOUGH-66S94W/28NWNW

Inspection Document #: 702801100

Garfield County, CO

NWNW Section 28 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/28NWNW
Location ID: 311564



Photo 1. Photo taken from the west shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801100

Inspection Photos
Location Name: CLOUGH-66S94W/28NWNW
Location ID: 311564



Photo 2. Photo shows where bubbles were observed to be rising in water around the wellhead.



Inspection Photos
Location Name: CLOUGH-66S94W/28NWNW
Location ID: 311564



Photo 3. Photos show equipment areas.



Inspection Photos
Location Name: CLOUGH-66S94W/28NWNW
Location ID: 311564



Photo 4. Photo shows an example of the interim areas. Vegetation appears dominated by introduced perennial grasses and native shrubs. Snow cover and dormant season prevented full assessment.

