

Inspection Photos

January 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335494

Location Name: CLOUGH-66S94W/29SWNE

Inspection Document #: 702801103

Garfield County, CO

SWNE Section 29 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/29SWNE
Location ID: 335494



Photo 1. Photos show production areas.

Inspection Photos
Location Name: CLOUGH-66S94W/29SWNE
Location ID: 335494




Photo 2. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801103

Inspection Photos
Location Name: CLOUGH-66S94W/29SWNE
Location ID: 335494



Photo 3. Photo shows an example of the interim areas. Note areas with perennial grass establishment (green) and areas where it appears perennials are absent and annual weeds dominate (red).



Inspection Photos
Location Name: CLOUGH-66S94W/29SWNE
Location ID: 335494



Photo 4. Photo shows Scotch thistle (List B Noxious). Note also, establishment of perennial grasses in midground and apparent lack of perennial grasses in foreground.