

Inspection Photos

API: 055-06154

Operator: PETROGLYPH OPERATING CO

Inspection Date: 1/6/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 1/6/2023

Inspection Photos



Photo 1. Facing east toward the access road. The site previously passed final reclamation inspection and surface owners are utilized the former access.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 1/6/2023

Inspection Photos



Photo 2. Facing east along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 1/6/2023

Inspection Photos



Photo 3. Center of the location facing south. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 1/6/2023

Inspection Photos



Photo 4. Center of the location facing east. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 1/6/2023