

Inspection Photos
Location Name: Miller 21-27
Location ID: 333238



Photo 1 WH sign.

Photo 2 WH



Inspection Photos
Location Name: Miller 21-27
Location ID: 333238



Photo 3 TB sign.

Photo 4 TB

Inspection Photos
Location Name: Miller 21-27
Location ID: 333238



Photo 5 Horizontal Heated Separator.

Photo 6 ECD



Inspection Photos
Location Name: Miller 21-27
Location ID: 333238



Photo 7 Gas Meter Run.