

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2023

Submitted Date:

01/09/2023

Document Number:

700901347**FIELD INSPECTION FORM**Loc ID 320462 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10651Name of Operator: VERDAD RESOURCES LLCAddress: 1125 17TH STREET SUITE 550City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
BEECHERL, ARTHUR	214-728-1840	Regulatory@verdadoil.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203823	WELL	PR	08/01/2022	GW	001-09383	BOX ELDER 32-20	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		39.953376,-104.679806	
Comment:						
Corrective Action:						Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Finkenbinder, Chane

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	Open Top		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Wells Served By Facilities Above**

**AirsID**

API Number	API Number	AirsID
001-09383		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

