

OTHER CHANGES

REMOVE FROM SURFACE BOND Signed surface use agreement is a required attachment

CHANGE OF WELL, FACILITY OR OIL & GAS LOCATION NAME OR NUMBER

From: Name SUSAN-65N65W Number 23SENE Effective Date: _____

To: Name _____ Number _____

ABANDON PERMIT: Permit can only be abandoned if the permitted operation has NOT been conducted. Field inspection will be conducted to verify site status.

WELL: Abandon Application for Permit-to-Drill (Form2) – Well API Number _____ has not been drilled.

PIT: Abandon Earthen Pit Permit (Form 15) – COGCC Pit Facility ID Number _____ has not been constructed (Permitted and constructed pit requires closure per Rule 905)

CENTRALIZED E&P WASTE MANAGEMENT FACILITY: Abandon Centralized E&P Waste Management Facility Permit (Form 28) – Facility ID Number _____ has not been constructed (Constructed facility requires closure per Rule 908)

OIL & GAS LOCATION ID Number: _____

Abandon Oil & Gas Location Assessment (Form 2A) – Location has not been constructed and site will not be used in the future.

Keep Oil & Gas Location Assessment (Form 2A) active until expiration date. This site will be used in the future.

Surface disturbance from Oil and Gas Operations must be reclaimed per Rule 1003 and Rule 1004.

REQUEST FOR CONFIDENTIAL STATUS

DIGITAL WELL LOG UPLOAD

DOCUMENTS SUBMITTED Purpose of Submission: _____

RECLAMATION

INTERIM RECLAMATION

Interim Reclamation will commence approximately _____

Per Rule 1003.e.(3) operator shall submit Sundry Notice reporting interim reclamation is complete and site is ready for inspection when vegetation reaches 80% coverage.

Interim reclamation complete, site ready for inspection.

Per Rule 1003.e(3) describe interim reclamation procedure in Comments below or provide as an attachment and attach required location photographs.

Field inspection will be conducted to document Rule 1003.e. compliance

FINAL RECLAMATION

Final Reclamation will commence approximately _____

Per Rule 1004.c.(4) operator shall submit Sundry Notice reporting final reclamation is complete and site is ready for inspection when vegetation reaches 80% coverage.

Final reclamation complete, site ready for inspection. Per Rule 1004.c(4) describe final reclamation procedure in Comments below or provide as an attachment.

Field inspection will be conducted to document Rule 1004.c. compliance

Comments:

The associated centralized facility is permitted separately (Location ID: 460173). A Surface Owner Variance Request has been submitted for the production facility and access road (Latham Ditch access) north of the production facility (Document Number 402431787). The location was accessed via the Latham Ditch road and temporary 2-track road connected to the production facility. This road remains for its historical purpose of field access. The portion of the access road specific to the Susan 1-23 well, has been fully reclaimed and returned to cropland.

ENGINEERING AND ENVIRONMENTAL WORK

NOTICE OF CONTINUED TEMPORARILY ABANDONED STATUS

Indicate why the well is temporarily abandoned and describe future plans for utilization in the COMMENTS box below or provide as an attachment, as required by Rule 319.b.(3).

Date well temporarily abandoned _____ Has Production Equipment been removed from site? _____

Mechanical Integrity Test (MIT) required if shut in longer than 2 years. Date of last MIT _____

SPUD DATE: _____

TECHNICAL ENGINEERING AND ENVIRONMENTAL WORK

Details of work must be described in full in the COMMENTS below or provided as an attachment.

NOTICE OF INTENT Approximate Start Date _____

REPORT OF WORK DONE Date Work Completed _____

- Intent to Recomplete (Form 2 also required)
- Request to Vent or Flare
- E&P Waste Mangement Plan
- Change Drilling Plan
- Repair Well
- Beneficial Reuse of E&P Waste
- Gross Interval Change
- Rule 502 variance requested. Must provide detailed info regarding request.
- Bradenhead Plan
- Status Update/Change of Remediation Plans for Spills and Releases
- Other _____

COMMENTS:

H2S REPORTING

Data Fields in this section are intended to document Sample and Location Data associated with the collection of a Gas Sample that is submitted for Laboratory Analysis.

Gas Analysis Report must be attached.

H2S Concentration: _____ in ppm (parts per million) Date of Measurement or Sample Collection _____

Description of Sample Point:

Absolute Open Flow Potential _____ in CFPD (cubic feet per day)

Description of Release Potential and Duration (If flow is not open to the atmosphere, identify the duration in which the container or pipeline would likely be opened for servicing operations.):

Distance to nearest occupied residence, school, church, park, school bus stop, place of business, or other areas where the public could reasonably be expected to frequent: _____

Distance to nearest Federal, State, County, or municipal road or highway owned and principally maintained for public use: _____

COMMENTS:

[Empty comment box]

Best Management Practices

No BMP/COA Type

Description

--	--

Operator Comments:

Please route to Chris Binschus.

Attached is the SOVR and final reclamation inspection for the former Susan 1-23 location. The former well site is located within a corn field. The corn within the disturbance area has high vigor and density that is comparable to the surrounding reference crop. No compliance concerns observed.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Kelley House, CPSS
 Title: Senior Soil Scientist Email: khouse@duraroot.com Date: 4/28/2021

Based on the information provided herein, this Sundry Notice (Form 4) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Binschus, Chris Date: 1/11/2023

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

--	--

0 COA	
-------	--

General Comments

User Group	Comment	Comment Date
Reclamation Specialist	The approval of this Form 4 is an acknowledgement that the document was received. It is not an approval of the final reclamation as the outcome of the methods will be determined on the ground during an inspection at a future date.	01/11/2023

Total: 1 comment(s)

Attachment List

Att Doc Num	Name
402673849	SUNDRY NOTICE APPROVED
402673863	OTHER
403287225	FORM 4 SUBMITTED

Total Attach: 3 Files