


**Inspection Photos**  
**Location Name: Esterling 44-33H**  
**Location ID: 428695**




**Photo 1 – Wellhead**



**Photo 2 – Flare and ECD**

**Inspection Photos**  
**Location Name: Esterling 44-33H**  
**Location ID: 428695**




**Photo 3 – Gas Meter and Compressor**



**Photo 4 – Separator**



**Inspection Photos**  
**Location Name: Esterling 44-33H**  
**Location ID: 428695**



**Photo 5 – Compressor**



**Photo 6 – Capacity Label missing**

Inspection Photos  
Location Name: Esterling 44-33H  
Location ID: 428695




Photo 7 – Tank Battery



Photo 8 – Tank Battery

**Inspection Photos**  
**Location Name: Esterling 44-33H**  
**Location ID: 428695**



**Photo 9 – Labels Missing**