





Comments:

The associated centralized facility, Hazen 23, 24-28 (Location ID 281040), is permitted separately and has been fully reclaimed and returned to cropland. The location was accessed via a preexisting north-south crop access road located off of CR 76. This road remains for its historical purpose of field access. All portions of the access road specific to the Hazen 23-28 well, have been fully reclaimed and returned to cropland.

**ENGINEERING AND ENVIRONMENTAL WORK**

NOTICE OF CONTINUED TEMPORARILY ABANDONED STATUS

Indicate why the well is temporarily abandoned and describe future plans for utilization in the COMMENTS box below or provide as an attachment, as required by Rule 319.b.(3).

Date well temporarily abandoned \_\_\_\_\_ Has Production Equipment been removed from site? \_\_\_\_\_

Mechanical Integrity Test (MIT) required if shut in longer than 2 years. Date of last MIT \_\_\_\_\_

SPUD DATE: \_\_\_\_\_

**TECHNICAL ENGINEERING AND ENVIRONMENTAL WORK**

Details of work must be described in full in the COMMENTS below or provided as an attachment.

NOTICE OF INTENT Approximate Start Date \_\_\_\_\_

REPORT OF WORK DONE Date Work Completed \_\_\_\_\_

- Intent to Recomplete (Form 2 also required)
- Request to Vent or Flare
- E&P Waste Mangement Plan
- Change Drilling Plan
- Repair Well
- Beneficial Reuse of E&P Waste
- Gross Interval Change
- Rule 502 variance requested. Must provide detailed info regarding request.
- Bradenhead Plan
- Status Update/Change of Remediation Plans for Spills and Releases
- Other \_\_\_\_\_

COMMENTS:

\_\_\_\_\_

**CASING PROGRAM**

(No Casing Provided)

**POTENTIAL FLOW AND CONFINING FORMATIONS**

(No Casing Provided)

**H2S REPORTING**

**Data Fields in this section are intended to document Sample and Location Data associated with the collection of a Gas Sample that is submitted for Laboratory Analysis.**

**Gas Analysis Report must be attached.**

H2S Concentration: \_\_\_\_\_ in ppm (parts per million) Date of Measurement or Sample Collection \_\_\_\_\_

Description of Sample Point:

\_\_\_\_\_

Absolute Open Flow Potential \_\_\_\_\_ in CFPD (cubic feet per day)

Description of Release Potential and Duration (If flow is not open to the atmosphere, identify the duration in which the container or pipeline would likely be opened for servicing operations.):

Distance to nearest occupied residence, school, church, park, school bus stop, place of business, or other areas where the public could reasonably be expected to frequent: \_\_\_\_\_

Distance to nearest Federal, State, County, or municipal road or highway owned and principally maintained for public use: \_\_\_\_\_

COMMENTS:

| <b><u>Best Management Practices</u></b> |                            |                           |
|---|----------------------------|---------------------------|
| <b><u>No</u></b>                        | <b><u>BMP/COA Type</u></b> | <b><u>Description</u></b> |
|   |                            |                           |

**Operator Comments:**

Please route to Chris Binschus.

Attached is the final reclamation inspection for the former Hazen 23-28 location. The former well site is located within a center pivot irrigated corn field. The corn within the disturbance area has high vigor and density that is comparable to the surrounding reference crop. No compliance concerns observed.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Kelley House  
Title: Senior Soil Scientist Email: khouse@duraroot.com Date: 4/26/2021

Based on the information provided herein, this Sundry Notice (Form 4) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Binschus, Chris Date: 1/11/2023

**CONDITIONS OF APPROVAL, IF ANY:**

| <u>COA Type</u> | <u>Description</u> |
|-----------------|--------------------|
| 0 COA           |                    |

**General Comments**

| <u>User Group</u>      | <u>Comment</u>   | <u>Comment Date</u> |
|------------------------|--|---------------------|
| Reclamation Specialist | The approval of this Form 4 is an acknowledgement that the document was received. It is not an approval of the final reclamation as the outcome of the methods will be determined on the ground during an inspection at a future date. | 01/11/2023          |

Total: 1 comment(s)

**Attachment List**

| <u>Att Doc Num</u> | <u>Name</u>            |
|--------------------|------------------------|
| 402670709          | SUNDRY NOTICE APPROVED |
| 402670717          | OTHER                  |
| 403287316          | FORM 4 SUBMITTED       |

Total Attach: 3 Files