

Inspection Photos

January 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 322425

Location Name: VASSAR-HEATH-66S94W/28NWNE

Inspection Document #: 702801109

Garfield County, CO

NWNE Section 28 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: VASSAR-HEATH-66S94W/28NWNE
Location ID: 322425



Photo 1. Photo taken from the east shows an overview of the location.

Inspection Photos
Location Name: VASSAR-HEATH-66S94W/28NWNE
Location ID: 322425



Photo 2. Photos show equipment areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801109

Inspection Photos

Location Name: VASSAR-HEATH-66S94W/28NWNE

Location ID: 322425



Photo 3. Photo shows an example of the interim areas. Introduced perennial grasses appear established.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801109