



00263293

RECEIVED

NOV 16 1979

Form Approved.

Budget Bureau No. 42-R1424

UNITED STATES OF THE INTERIOR
GEOLOGICAL SURVEY, OIL & GAS CONS. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
Chevron U.S.A. Inc.
3. ADDRESS OF OPERATOR
P. O. Box 599, Denver, Colorado 80201
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 641' FSL & 658' FEL (SE SE)
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
- FRACTURE TREAT ☐
- SHOOT OR ACIDIZE ☐
- REPAIR WELL ☐
- PULL OR ALTER CASING ☐
- MULTIPLE COMPLETE ☐
- CHANGE ZONES ☐
- ABANDON* ☐
- (other) ☐

SUBSEQUENT REPORT OF:

- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☒

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was plugged and abandoned as follows: ~~8/29~~ 8/29- Plug Date

1. MI.
2. Set plug at + 3100' w/25 sx "G"
+ 600' w/15 sx "G"
Surface w/10 sx "G" in 10-3/4" csg.
3. Welded plate on 10-3/3" csg. Installed pkr.
4. Cleaned up location.

EXHAUSTED
OIL WELL

No additional surface
disturbances required
for this activity.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

Assistant

SIGNED

Yolanda Pamar

TITLE Engineering

DATE October 4, 1979

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DIRECTOR
O&G CONS. COMM.

DATE

NOV 20 1979

DVR	
FJP	
HHM	
JAM	
JJD	
RLS	
CGM	