

Inspection Photos

January 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335193

Location Name: CLOUGH-66S94W/22SWSW

Inspection Document #: 702801117

Garfield County, CO

SWSW Section 22 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/22SWSW
Location ID: 335193



Photo 1. Photo taken from the west shows an overview of the lower/southern portion of the location.



Inspection Photos
Location Name: CLOUGH-66S94W/22SWSW
Location ID: 335193



Photo 2. Photo taken from the west shows an overview of the upper/northern portion of the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801117

Inspection Photos
Location Name: CLOUGH-66S94W/22SWSW
Location ID: 335193



Photo 3. Photos show equipment areas. Wildlife egress BMP not observed at well API # 045-07826 cellar (right).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801117

Inspection Photos
Location Name: CLOUGH-66S94W/22SWSW
Location ID: 335193



Photo 4. Photos show lack of stabilization/compaction at the upper/northern portion of the location.

Inspection Photos
Location Name: CLOUGH-66S94W/22SWSW
Location ID: 335193



Photo 5. Photo shows an example of the interim areas. Introduced perennial grasses appear established.

