

Inspection Photos

January 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 323912

Location Name: CLOUGH-66S94W/28NENE

Inspection Document #: 702801119

Garfield County, CO

NENE Section 28 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/28NENE
Location ID: 323912



Photo 1. Photo taken from the east shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801119

Inspection Photos
Location Name: CLOUGH-66S94W/28NENE
Location ID: 323912



Photo 2. Photo shows the methanol tank at the northwest of the location. Labels are in disrepair.



Inspection Photos
Location Name: CLOUGH-66S94W/28NENE
Location ID: 323912




Photo 3. Photos show equipment areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801119

Inspection Photos
Location Name: CLOUGH-66S94W/28NENE
Location ID: 323912



Photo 4. Photo shows an example of the interim areas. Introduced perennial grasses appear established.

