

Inspection Photos

API: 009-06453

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/10/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06453 | Date: 1/10/2023

Inspection Photos



Photo 1. Facing northeast toward the location. The equipment and debris have been removed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06453 | Date: 1/10/2023

Inspection Photos



Photo 2. Facing north at the location. The vegetation has not yet established to reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06453 | Date: 1/10/2023

Inspection Photos



Photo 3. Facing back to the west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06453 | Date: 1/10/2023

Inspection Photos



Photo 4. There is a permitted water well adjacent to the location and tank s not associated with the abandoned wellsite..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06453 | Date: 1/10/2023

Inspection Photos



Photo 5. Facing northwest toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06453 | Date: 1/10/2023