

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/13/2023

Submitted Date:

01/13/2023

Document Number:

690010714

**FIELD INSPECTION FORM**Loc ID 446179 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		COGCCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446870	TANK BATTERY	AC	07/22/2016		-	BEDDO 3-25/BED D O6-25 O SA 34003469	AO

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		

Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		40.202550,-104.833740
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.201700,-104.834840
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		40.201700,-104.834840
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	48 Bbl				
Other (Type)					

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:		Date:				
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.202550,-104.833740	
Comment:						
Corrective Action:		Date:				
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:		Date:				
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV CONCRETE		40.201860,-104.834640	
Comment:						
Corrective Action:		Date:				
Paint						
Condition						
Other (Content)						
Other (Capacity)	43 Bbl					
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:		Date:				
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		40.201860,-104.834640	
Comment:						
Corrective Action:		Date:				
Paint						
Condition	Adequate					
Other (Content)						

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above****AirsID**

API Number

API Number

AirsID

123-19665

123-19541

123-08323

123-21164

123-18939

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 446870 Type: TANK API Number: - Status: AC Insp. Status: AO**COGCC Comments**

Comment	User	Date
<a href="#">Routine wellhead inspection.</a>	carlilec	01/13/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690010715	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5982455">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5982455</a>