



## LEASE INSPECTION FORM

Date 7/24/85  
Operator DYCO Field BUCK PEAK  
Lease Name & No. FEDINEC 1-14 County MOFFAT  
Tank Battery No. N/A Location 14 - 6N-90W  
Legal Description  
Type of Inspection PTA / wellsite  
Water Inflow \_\_\_\_\_ (Bbls. Per Day)

## RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)

## Type of Tank

SKIM TANK CUT OFF 9 5/8" ? CASING, FULL W/ CEMENT  
INSIDE 5' CONCRETE PIPE ACTING AS CONDUIT / CELLAR

Pit No. 1 \_\_\_\_\_  
TRASH & DEBRIS ALL OVER LOCATION

Pit No. 2 \_\_\_\_\_  
120' X 60' X 20', RESERVE PIT, FENCED, OPEN, UNLINED,

Pit No. 3 VERY DIRTY H<sub>2</sub>O

ADDITIONAL PITS WOULD GUESS ~ 200 yd<sup>3</sup> EARTHWORK MOVED TO BUILD  
LOCATION ON SIDE OF HILL, NEEDS RE-CONTOURING & SEEDING

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety  
- Conditions, Etc.)

RECOMMENDED ACTION (If Required) PLACE IN WELL FILE, NEEDS RECHECKING

INSPECTOR JJK