

Inspection Photos

January 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334799

Location Name: COUEY-67S92W/8NENW

Inspection Document #: 702801147

Garfield County, CO

NENW Section 8 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: COUEY-67S92W/8NENW
Location ID: 334799



Photo 1. Photo taken from the south shows an overview of the location.



Inspection Photos
Location Name: COUEY-67S92W/8NENW
Location ID: 334799




Photo 2. Photos show production areas. A tank battery sign is absent (right).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801147

Inspection Photos
Location Name: COUEY-67S92W/8NENW
Location ID: 334799



Photo 3. Photos show examples of location interim areas. Sagebrush appears established in portions of the interim areas. Perennial herbaceous understory is not evident. Portions of the location appear to have either high establishment or debris accumulation of Russian thistle (annual, undesirable plant species).

